




Oil Pump



Tianjin Geortor Auto Parts Co., Ltd.

2-1-1703, Luolan Garden, YongAn Rd. Hexi Dist. Tianjin, China.

Web-site: www.gerotorauto.com E-mail: info@gerotorauto.com

Tel: 0086-22-23286383

Fax: 0086-22-83863296

O.E.M names and numbers are used for reference purpose only.



78 3020

Replacing 4132F043
3638595M91

Servicing MASSEY FERGUSON 396
399 3085 3095 3115 4260
4270 6160 6170



78 3021

Replacing 4132F056
4222282M91

Servicing MASSEY FERGUSON
8925 8926 8937 8939 760
860 865 960 965



78 3022

19T

Replacing 4132F051
3640908M91

Servicing MASSEY FERGUSON
8925 8926 8937 8939
Perkins 1004



78 3023

Replacing 4132F057
3641171M91

Servicing MASSEY FERGUSON
3075 320 3125 6180 6190
6270 8120 8220 Perkins
1006



86 6491

Replacing U5MK8265

Servicing PERKINS 103 403D-11
404C-15



86 6492

Replacing U5MK8266

Servicing PERKINS 100 Series
400Series 403C 404C



86 6493

Replacing U5MK8267

Servicing PERKINS 403D 404D
404C



86 6494

Replacing 4132F071
4225294M1

Servicing PERKINS 1103 1104 ,
MASSEY FERGUSON
3425 410 420 430 8925



86 6495

Replacing 41314137
747292M91

Servicing PERKINS, MASSEY
FERGUSON 1014 1024 1114
1134 1250 2620 2640 2725
3080 3650 530 565 699 750
800 805



86 6496

Replacing 41314136
747293M91

Servicing PERKINS 6.354 , MASSEY
FERGUSON 830 840 845 750
660 665 699 560 565 3650
3630 3610 3090 3080



86 6497

Replacing 41314067
736012M91

Servicing PERKINS,
A6.3541 MASSEY
FERGUSON 3505 399




86 6498

Replacing 3551800101
05808

Servicing Mercedes-benz T2/L

 86 6499 <i>Replacing</i> 4031802801 51051006135 07988 <i>Servicing</i> Mercedes-benz,NEOPLAN, MAN	 86 6500 <i>Replacing</i> 3802278 <i>Servicing</i> CUMMINS:6CT8.3	 86 6501 <i>Replacing</i> 3937404 <i>Servicing</i> CUMMINS:6BT CASE MAXXUM 5130 5140 5150
 86 6502 <i>Replacing</i> 4897481 504047581 <i>Servicing</i> CUMMINS:6BT,IVECO	 86 6503 <i>Replacing</i> 4897480 <i>Servicing</i> IVECO Eurocargo Eurofire	 86 6504 <i>Replacing</i> 3973398 <i>Servicing</i> CUMMINS 4B 6B QSB3.9
 86 6505 <i>Replacing</i> 3991123 <i>Servicing</i> CUMMINS 6CT	 86 6506 <i>Replacing</i> 4003950 <i>Servicing</i> CUMMINS L10 M11	 86 6507 <i>Replacing</i> 3971544 <i>Servicing</i> CUMMINS 6B 6BT 6BTA 6D107 (PC200-8)
 86 6508 <i>Replacing</i> 4939587 <i>Servicing</i> CUMMINS 6BT MAXXUM 5130 5140 5150	 86 6509 <i>Replacing</i> 4939585 <i>Servicing</i> CUMMINS 4BT CASE HI MAXXUM 5120 5220	 86 6520 <i>Replacing</i> 3521806301 05298 <i>Servicing</i> Mercedes-benz:OM352A

 86 6521 <i>Replacing</i> 3551801601 08354 <i>Servicing</i> Mercedes-Benz LSeries OM355	 86 6524 <i>Replacing</i> 3661800401 01962 <i>Servicing</i> Mercedes-benz:OM366	 86 6525 <i>Replacing</i> 4031801701 51051006133 07685 <i>Servicing</i> Mercedes-benz:OM403, MAN
 86 6526 <i>Replacing</i> 4231802501 02447 <i>Servicing</i> Mercedes-benz: MK NG SK OM423 MAN F90 D2865 D2866	 86 6527 <i>Replacing</i> 4571800201 173725 <i>Servicing</i> Mercedes-benz:OM457	 86 6528 <i>Replacing</i> 6461801601 101086 <i>Servicing</i> Mercedes-benz
 86 6530 <i>Replacing</i> 5421800201 19435 <i>Servicing</i> Mercedes-benz	 86 6531 <i>Replacing</i> 4031802701 51.05100.6155 07987 <i>Servicing</i> Mercedes-benz ,MAN	 86 6532 <i>Replacing</i> 5411800715 09415 <i>Servicing</i> Mercedes-benz;Actor Axor NG SK
 86 6540 <i>Replacing</i> 479317 1545824 22054 <i>Servicing</i> VOLVO: F10 FL10 NL10 TAD1030 TMD102 TWD1030	 86 6541 <i>Replacing</i> 479319 1545119 <i>Servicing</i> VOLVO: F10 FL10 N10 NL10 TD100G	 86 6542 <i>Replacing</i> 471733 477547 <i>Servicing</i> VOLVO: FE7 FL6 FL7 FS7 B6 B7 TD63 TD71 TD73



86 6543

Replacing 1318091
1369981
09977
Servicing SCANIA:DS11



86 6544

Replacing 263161
09911
Servicing SCANIA:DS14



86 6545

Replacing 1426449
18793
Servicing SCNIA 3 4 F K N P G R T



86 6546

Replacing 194838
03246
Servicing SCNIA



86 6550

Replacing 4132F012
3640287M1
Servicing MF3065 3370 20 JCB 214 215
217 3CX 4CX 5CX 520S
VOLVO BM 2200 2204 2250
2254



86 6551

Replacing 41314182
3638631M91
Servicing PERKINS 4.236 4.248
4.212 MF440



86 6555

Replacing 02934430
Servicing DEUTZ F4L1011



86 6556

Replacing 04102478
Servicing DEUTZ BF3L2011 F4L2011
F4M2011



86 6557

Replacing 5411800001
19434
Servicing Mercedes-benz ACTROS ,
ACTROS MP2 / MP3



86 6558

Replacing 7408170261
8170261
171742
Servicing RENAULT TRUCKS
VOLVO



86 6559

Replacing 5010477184
176782
Servicing RENAULT TRUCKS,IVECO



86 6562

Replacing 41314189
3638633M91
Servicing Massey Ferguson:50, 65,
155, 158, 165, 260, 560,
765 A4.203 AD4.203



B 20163

Replacing 23527448

Servicing Detroit 60 14L



B 20164

Replacing 23505886

Servicing Detroit 60 12.7L



B 20165

Replacing 1192924
1898777

Servicing CAT C7 3126 3116 IT28G
IT38G IT62G IT62H



B 20166 66mm

Replacing 1614111
4N0733

Servicing CAT 3406T



B 20167

Replacing 15110-1471

Servicing Hino EL100 EP100 EM100



B 20168

Replacing 15110-1461

Servicing HINO EF750



B 20169

Replacing 1614112
4N0735

Servicing CAT 3406



B 20170

Replacing 1614113
0R9449

Servicing CAT C15 3408T



B 20171

Replacing 6211-51-1000

Servicing KOMATSU SA6D1401



IB 00001

Replacing 3926203

Servicing CUMMINS 4BT



IB 00002

Replacing 3042378
AR9834

Servicing CUMMINS NT855



IB 00003

Replacing 3821579

Servicing CUMMINS NTA855

 IB 00004 <i>Replacing</i> 3941742 <i>Servicing</i> CUMMINS 6BT	 IB 00005 <i>Replacing</i> 3937027 <i>Servicing</i> CUMMINS 4BT	 IB 00006 <i>Replacing</i> 04234148 <i>Servicing</i> DEUTZ F6L913 TCD914 L06
 IB 00007 <i>Replacing</i> 3966840 <i>Servicing</i> CUMMINS 6CT	 IB 00008 <i>Replacing</i> 04143644 <i>Servicing</i> DEUTZ F6L413	 IB 00009 <i>Replacing</i> E1NN6600DC 83956424 <i>Servicing</i> Ford 231 233 234 250 260 445 450 455 540 2000 2100 3000 2100 4000 4100 4600 5000 5200 5700
 IB 00010 <i>Replacing</i> E1NN6600CC 83956421 <i>Servicing</i> Ford 555CT 655 755 5030 6610 6710 6810 7000 7200 7410 7600 7610 7710	Pictures coming soon  IB 00011 <i>Replacing</i> 4939586 <i>Servicing</i> CUMMINS 4BT	 IB 00018 <i>Replacing</i> 4935792 <i>Servicing</i> CUMMINS 6BT
 IB 00022 <i>Replacing</i> 02130440 4158299 <i>Servicing</i> DEUTZ 912D 4 CYLINDER D4006 D7207 INTRAC 2002 INTRAC 2003	 IB 00025 <i>Replacing</i> 612600070033 <i>Servicing</i> WD615	 IB 20076 <i>Replacing</i> 14091485 93258835 SKPM62 <i>Servicing</i> CHEVROLET C10/C20



IB 20169

Replacing 41314078
3638632M91

Servicing PERKINS A3.144 A3.152
MF240 D3.152



IB 20170

Replacing 04191262
02233688

Servicing DEUTZ F2L511



IB 20171

Replacing 0336 5893

Servicing DEUTZ F6L614A



IB 30001

Replacing 740.1011014-30

Servicing KAMAZ 4310 43101 43114
43118 4326 5315 5320 53212
5410 54112 55102 5511
7403.10-260